State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt Governor

Kathleen Clarke Executive Director Lowell P. Braxton Division Director 1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801

801-538-5340 801-359-3940 (Fax) 801-538-7223 (TDD)

INSPECTION REPORT

Partial: XXX	Complete:	Exploration: _	
Inspection Date &	Time: <u>09/05/2</u>	2001 / 10:00am-2:00p	.m.
Date of La	st Inspection:	08/13/2001	

Mine Name: <u>Dugout Canyon Mine</u> County: <u>Carbon</u> Permit Number: <u>C/007/039</u>								
Permittee and/or Operator's Name: <u>Canyon Fuel Company</u>								
Business Address: PO Box 1029, Wellington, Utah 84542								
Type of Mining Activity: Underground XXX Surface Prep. Plant Other								
Company Official(s): <u>Ken Payne</u>								
State Official(s): <u>Stephen J. Demczak, Karl Houskeeper</u> Federal Official(s): <u>None</u>								
Weather Conditions: Sunny, 70's								
Existing Acreage: Permitted 7083.71 Disturbed 22.65 Regraded Seeded Seeded								
Status: Active XXX								

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For partial inspections check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	<u>N/A</u>	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[X]		[X]	П
2.	SIGNS AND MARKERS	[X]	\Box	[X]	\Box
3.	TOPSOIL	[X]	П	[X]	\Box
4.	HYDROLOGIC BALANCE:				
	a. DIVERSIONS	[X]	\Box	[X]	\Box
	b. SEDIMENT PONDS AND IMPOUNDMENTS	[X]	\Box	[X]	\Box
	c. OTHER SEDIMENT CONTROL MEASURES	[X]	П	[X]	\Box
	d. WATER MONITORING	[X]	\Box	[X]	\Box
	e. EFFLUENT LIMITATIONS	\Box	\Box	\Box	\Box
5.	EXPLOSIVES	\Box	\Box	\Box	\Box
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	\Box	\Box	\Box	\Box
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS		\prod	\square	П
8.	NONCOAL WASTE	[X]	\Box	[X]	\Box
9.	PROTECTION OF FISH, WILDLIFE AND RELATED				
	ENVIRONMENTAL ISSUES	\Box	П	\Box	\Box
10.	SLIDES AND OTHER DAMAGE	\Box	\Box	\Box	\Box
11.	CONTEMPORANEOUS RECLAMATION	<u>[]</u>	Ш	\Box	
12.	BACKFILLING AND GRADING	\Box	П	\Box	. []
13.	REVEGETATION	\Box	Ц		\Box
14.	SUBSIDENCE CONTROL	\Box	\Box	\Box	П
15.	CESSATION OF OPERATIONS	\Box	\Box	П	П
16.	ROADS:				
	a. CONSTRUCTION/MAINTENANCE/SURFACING	\Box	\Box	П	\Box
	b. DRAINAGE CONTROLS		\Box	\coprod	\Box
17.	OTHER TRANSPORTATION FACILITIES		\Box		П
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	[X]	\Box	[X]	П
19.	AVS CHECK (4th Quarter- April, May, June)			П	\Box
20.	AIR QUALITY PERMIT	\Box			\Box
21.	BONDING & INSURANCE	П	\Box	П	\Box

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: <u>C/007/039</u>

DATE OF INSPECTION: <u>09/05/2001</u>

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

The permittee has submitted an amendment to drill a water well into an old abandon coal mine. Its use will be for supplying water for the underground mining and fire suppression.

2. SIGNS AND MARKERS

The permittee has placed a topsoil sign on the soil located at the leach field. This is a temporary sign during construction. The material will be spread out on the leach and then will be seeded. This will be final reclamation of this area.

3. TOPSOIL

The permittee has gathered topsoil from the leach field and is storing it at the leach field. The topsoil pile is completely protected by a silt fence. This material will be spread out after the construction of the leach field. The permittee will seed afterwards.

4A. HYDROLOGIC BALANCE: DIVERSIONS

The diversions appeared to be capable of functioning as designed. The majority of the diversions are concrete lined.

Several other diversions had been cleaned since the last inspection.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The permittee has finished cleaning out the sediment pond. This action was approved in a previous amendment. The material was taken to Banning Loadout.

4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

The leach field is bermed to prevent off site impact during construction. This berm will stay in-place after construction.

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: C/007/039

DATE OF INSPECTION: 09/05/2001

4D. HYDROLOGIC BALANCE: WATER MONITORING

Water samples were taken for second quarter, but, the permittee has not electronically submitted the information to the Division. This information will be sent to the Division by the end of the quarter. The water sampling for third quarter will be taken by the end of the quarter.

8. NONCOAL WASTE

The mine site was free of non-coal waste material.

18. SUPPORT FACILITIES/UTILITY INSTALLATIONS

The permittee is in the process of constructing a leach field. This action was approved by the Division.

Inspector's Signature:

Kephen J. Demczak 🖊 #3

Date: September 14, 2001

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

sd

cc:

James Fulton, OSM Rick Olsen, Canyon Fuel Dave Spillman, Canyon Fuel Chris Hansen, Canyon Fuel Price Field office

O:\007039.DUG\Compliance\2001\p 0905.wpd